

In the following the CONTENT of each CICIND Report is provided as Microsoft Word File produced with OCR from the scans. This allows the user to search effectively for authors, titles and subjects in all forty three scanned CICIND Reports.

CICIND REPORT 1-1 Year: 1985

Comparison of oncrete Chimneys, Designed According to Various Codes
— P. Noakowski
Cross Wind Oscillations of Cylindrical Chimneys at Low Reynolds Numbers
— H. Van Koten
Thermally Induced Deflections of a Chimney Foundation
— F. Aschieri and F. Ulliana
Investigation Concerning Fatigue Behaviour of Concrete Specimens
— P. Noakowski

CICIND REPORT 2-1 Spring 1986

Evaluation of Methods of Predicting the Across-wind Resporise ot Chimneys
— Albert F. Daly
A Design Approach to Evaluating Across Wind Response of Chimneys
— B.J. Vickery
ACI 307 Latest Proposals for the Design of Reinforced Concrete Chimneys
— Wadi S. Rumman

CICIND REPORT 2-2 Autumn 1986

Investigations of the Comparability of Different Standards for the Determination of the Acid Resistance of Bricks
— H. Bottenbruch and H. Posch.
Chimney Foundations
— Roger Thompson
Creep and Shrinkage Effects on the Stress State of Chimneys Built with Sliding Formwork
— Prof. A. Migliacci, Prof. F. Mob, P. Riva

CICIND REPORT 3-1 Spring 1987

Proceedings of a Symposium on advanced inspection techniques. Dynamic Structural Testing of Torre Valdaliga Nord Power Plant's 250 m high chimney
— E.M. Da Rin
The Dynamic Monitoring of Industrial Chimneys
— J. F. Sageau
The LADI R System for remote vibration measurements
—A. Rota
Hot Camera Chimney Inspections
—J.D. Miller
Introduction to Thermography
L. Van Chastelet

CICIND REPORT 3-2 Autumn 1987

Reconditioning Measures on Power Plant Chimneys Because of an Increase in Boiler Output or Conversion to Operation with FGD-System
— B.Ertz
Desulphurisation Systems; Effect on Operational Conditions of Chimneys
— F. Henseler
Innovative Solutions to Chimney Lining Problems
— R.W.Snook

CICIND REPORT 4-1 Spring 1988

Circular Reinforcement of Chimneys under Load of Temperature and Wind
— P. Noakowski
Major Repair Executed on a Small Concrete Chimney
—A.Coradi
Wind Regime in Hong Kong
—Tam Cheuk-ming

CICIND REPORT 4-2 Autumn 1988

Vortex — induced vibrations of a steel chimney
— T. Karna
Vibration monitoring of tall concrete chimneys
— E.M. Da Rin and S. Stefani
Some Comments on the deterioration of Industrial provoked by changes in their duty
— A. Tzincoca
Concrete materials for chimneys in marine tropical
— J.H.A Thornely

CICIND REPORT 5-1 Spring 1989

Design aspects of chimneys at Austrian Thermal Power Plants

— H. Nussbaumer & L. Prah

Design and construction of the Mellach plant chimney incorporating a desulphurisation plant

— H. Brunold & M. Feischl

Chimney Foundations

— H. van Koten

Piled foundation at the 250 m tall multi-flue chimney at Torre Valdaliga Nord Power Plant

— F. Ulisse, R. Caruana & S. Stefani

CICIND REPORT 6-1 Spring 1990

The Internal European Market in 1992

— Gunter Breitschaft

The Eurocodes

— Hans Joachim Seyfert

Content of the Eurocodes

— Horst Nieser

CICIND REPORT 6-2 Autumn 1990

Corrosion Protection of Steel Liners in Chimneys Serving Plants with FGD on Stream

— M. Beaumont, Dott. Ing. A.F. Uliana und Dott. Ing. M. Poli

Protection of an FGD Plant: Surface Treatment of Steel After Several Years of Operation

— J.L.S. van der Sloot

Protection and Maintenance of Concrete Chimneys

— Dr B.R. Muller

Cracking Control in Concrete Chimneys

— P. Noakowski and K. van Dornick

CICIND REPORT 7-1 Spring 1991

The Latest Technology and Quality Control of Steel Stacks in Japan

— Katsuyuki Hirao

Quality Assurance in the Republic of South Africa

— TV. Engelbrecht

What is the Meaning of Quality Assurance and To What End do We Pursue It?

— Dipl.-Ing. W. Erdmann

A New Philosophy in Concrete Construction

— Alvaro G. Nesequer

Quality Assurance of Steel Stacks in the USA

— R.M. Warren and S.L. Reid

Quality Assurance to BS 5750

— Max Beaumont

CICIND REPORT 7-2 Autumn 1991

Collapse of a 150m Tall Concrete Chimney

— Dipl.- Ing. Meiche

Monitoring of Chimney Performance

—F. Aschieri

Optimisation of the Top Part of Chimneys, With Regard to the Downwash Effect

— H. Ruscheweyh and B. Ertz

Hot Air Jacket for 150m Multi-Flue Steel Liners in a 15Dm Tall Chimney

— J.F. Davenport and D. T. Smith

Concrete Chimneys With Cast-in-Situ Linings of Polymer Cement Concrete

— V.G. Lebedev

CICIND REPORT 8-1 Spring 1992

USA Experience with Linings and Coatings for Concrete Chimneys

—J. C. Sowizal

Behaviour of Linings in the Chimneys of Electricite' De France

—G. Thoraval

Thermal Stress Static in Acid-Resisting Brickwork Linings for Industrial Chimneys

— E.M. Da Rin and A.F. Uliana

Design and Construction of Elliptical Brickwork Linings

—Klaus van Dornick and Piotr Noakowski

CICIND REPORT 8-2 Autumn 1992

A method of refurbishing old brick chimneys to suit modern environmental conditions

— M. Beaumont

Repair and rebuilding of a steel chimney, using reinforced concrete

— J. Laegaard

A composite method for crack repair and restoration of a reinforced concrete chimney

— H. Wippel, P. Steidle and I. Wendt

Behaviour of the Liner support system in a multi-flue chimney

—P. Noakowski, K. van Dornick

Rehabilitation of two concrete chimneys, diameter 5m and height 100m

— P. Toscano

Unconventional methods for concrete chimney repair

— V.H. Frumkin

CICIND REPORT 9-1 Spring 1993

Prevailing Conditions at the top of chimneys

— F. Henseler

Protecting the outer surfaces of chimneys downstream of flue gas cleanup equipment

—W. Erdmann

Corrosion deterioration in reinforced concrete chimneys

—P. Moncarz, et al

The behaviour of reinforced concrete under the action of repeated heating and wetting

—A.P. Krichevsky

The estimation of effects of localised defects on the integrity of concrete chimneys

—V.M. Levin

Demolishing chimneys

— M. Ganopolskiy. Russia

CICIND REPORT 9-2 Autumn 1993

Consequence of a sudden interruption of gas flow

— G. Haag, P. Noakowski

Sealing joints for chimney liners

— M. Poli

A novel solution to a difficult chimney erection problem

— J. De Jong

Construction of chimneys and towers using slip form and jump form systems

— B. Kremser

Design of concrete chimneys in regions of high seismicity

— A. Alsop, E. Booth, J. Blanchard

Safety in the CICIND concrete and steel chimney codes

— H. Van Koten

Safety in the CICIND Concrete Chimney Code

— H. Bottenbruch

CICIND REPORT 10-1 Spring 1994

Chimney business: Atmosphere of crisis or opportunity

— F. Henseler

A Long term prognosis on the development of industry and energy consumption in Germany

—W. Priebe

Elastomeric seals fitted downstream of FGD in Drax Power Station

— T.R. Brown & W. Evans

Protection of steel and concrete surfaces in the FGD environment

— S. Collier

Shell to flue impact damping for dual wall and multiflue steel chimneys

— AM. Warren & S.L. Reid

Optimum control of chimney vibration

—H. Hirsch & M.A. Rosa

CICIND REPORT 10-2 Autumn 1994

Monitoring of Power Station Chimneys

— J.F. Sagean

Modern Principles in Concrete Repair of Chimneys

—P. Holdt

Quality Control Systems for Hastelloy Chimney Lining, with Wall-papering Technique

— F. Stella

Cross-Wind Vibrations of Cylinders at Small Scruton Numbers

— H. van Koten

Mistuned Mass Dampers

— N.R. Bierrum

— The Turkish Earthquake Resistant Design Codes, with Reference to Industrial Chimneys

— MIV. Aydinogtu

Behaviour and Maintenance of Coatings in Chimneys of EDF Fossil-Fired Power Plants
— G. Thoraval & B. Clatot
Brick Lining Reinforcement with Protective Coating
— D. Busch , P. Noakowski

CICIND REPORT 11-1 Spring 1995

The RAL Quality Control System for Expansion Joints and Seals in Industrial Chimneys
— H. Tuckmantel
Earthquakes in Turkey — A case study of die Erzincan earthquake
—A.M. Antal
Mathematical modelling of turbulent wind flow around chimneys
— B. Younis
The stress distribution in chimneys due to wind pressure
— H. van Koten
Effect of flange geometry on the strength of bolted joints
— G. Pinfold
Lining support slabs in multiflue chimneys
— D. Busch, P. Noakowski
Design and construction of a cluster of 7 steel chimneys
— J. Bouten
Some unusual or unique chimneys
— D.T. Smith
Finishing a reinforced concrete chimney 7 years after interruption of the construction
— R. Ciesielski

CICIND REPORT 11-2 September 1995

Unexpected behaviour of some r. c. chimneys in Polish heat-generating plants
— M. Lechman & P. Lewinski
Stack problems and consequential costs
— I.G. Stundish
Comparison of concrete chimneys designed to ACI307, 1988 and to CICIND Model Code
— N.R. Bierrum
Chimney life extension in power stations
— J.M. Del Solar & C. Gonzales
Cost optimisation methods in chimney design
— M. Angelides
Profile of the MASS System
— H. Qmura
Experience with vortex excited oscillations of steel chimneys
— H. Ruscheweyh
Shell/Liner interactions on a flexible foundation
—B.J. Vickery
Design of a sandwich GRP liner incorporating thermal insulation
— G. Oudin
A new calculation method for the Cordemais chimney
— Y. Berthet & D. Chauvel

CICIND REPORT 12-1 March 1996

Progress in FGD chimneys
— F. Henseler
Experience of various lining materials in an FGD pilot plant
— F. Uliana, P. V. Scolari und M. Poli
Innovative design aspects of the 200m concrete chimney, Pocerady, Czech Republic
— P. Noakowski, 31. Breddermann, H. Hes. C. Buizer; B. Jezek & J. Sipek
Application of a high nickel alloy liners in chimneys in FGD service
— W. Plant
Installation and operation of titanium linings in FGD ductwork and stacks
— D. K. Peacock und J. S. Grauman
Repairing chimney liners using borosilicate glass blocks
— E. den Boogert, A. de Kreij und N. W. Huxley
Application of protective linings in flues and ductwork in FGD environment
— S. Collier
Temperature effects in chimneys and steel fibre shotcrete for reinforcement
— A.P. Krichevsky
Calculation of chimney vibrations by transfer matrix method
— W. Jalil
The effect of spiral gas flow on steel chimney liners
— N.R. Bierrum

CICIND REPORT 12-2 September 1996

- Wind load provisions of ASCE 7-95 for flexible structures
— A. Kareem
- Vibration control of stacks by passive damping devices — Numerical and experimental study of the damping effect of inner tubes inside a steel stack and a new dynamic vibration absorber
— H. Ruscheweyh, C. Kammel & C. Verwiebe
- Wind Load Stresses in Steel Chimneys
— J.G. Turner
- Damage by Hurricane Andrew to reinforced concrete stacks in Florida
— P. Moncarz & P. Noakowski
- Thermal effects on We Florida Power & Light Co's Turkey Point Unit 2 Chimney
— R.A. Cook, J.T. Hatfield, W.F. Brannen & T. Joseph
- A history of the development of fluor-elastomer compounds for use in flue expansion joints
— J.G. Bauerle
- Two phase flow in chimneys — the origin and transport of moisture and particles in the chimney flue
— J. Sipek & P. Snop
- Optimum Dimension and reinforcement of concrete foundation blocks for steel chimneys
— H.van Koten
- Comparison of Concrete Chimney Designs per ACI 307-95 and CEN
— N.R. Bierrum & H. Von Koten
- ACI 307-95 — major revisions from AG 307-88 and latest direction
— V. Bochicchio
- Report on revisions to ASME/ANSI STS-1 — Steel Stack Standard
— R.M. Warren

CICIND REPORT 13-1 March 1997

- The use of FRP in Flue Gas Desulfurization Processes
— J. Kamody
- Large Diameter GRP Liners in the United States
— A.H. Ershig
- Design of FRP Equipment for FGD Systems
— J. Ness
- Structural Behaviour of a 160m chimney with a GRP Liner with 2.5m diameter
— G. Di Poi
- Phenolic Resins in Stack and Flue Service
— A.R. Heppenstall
- Design of Sandwich GFRP Chimneys
— B.M. Maslov
- Structural Design Rules for Steel Chimneys — The Preparation of Eurocode 3, Part 3.2
— B.W. Smith, A.S. Karamonos, G. Sedlacek, C. Verwiebe
- Chimney Design Practice in Greece
— M. Angelides
- Thermal Stresses in Brickwork Linings Downstream of FGD
— M. Lechman

CICIND REPORT 13-2 September 1997

- On the Failure Mechanisms of Reinforced Concrete Chimneys
— G.I. Schueller and C.G. Buchee
- Failure Probability and Load Factors
— N. R. Bierrum
- Ductility of Reinforced Concrete Chimneys Subject to Earthquake Excitation
— J.L. Wilson
- Seismic Design in Rumania and Evaluating Existing Chimneys in Seismic Areas
— V. Rosetnic
- Design of Reinforced Concrete Chimney of Shih-Lin Incinerator Plant
— T.S. Fu, Y.C. Chen, L.C. Mu
- FGD Past Experience has shown that Failures can be prevented
— F. Henseler
- Chimneys for Wet Scrubber Power Plant Applications
— J. Sowizal
- Cladding to Reinforced Concrete Chimney Windshields
— N.R. Bierrum
- Repair of a Damaged Concrete Chimney using a Steel Sheath
— G. Pinfeld
- Steel Chimney Inspection
— M. Beaumont
- Assessment of Chimney Life
— A. Fellows

CICIND REPORT 14-1 March 1998

- The Use of GRP to Repair Chimney Liners in an FGD Environment
— R. Schmidt
- Assurance of the Availability of Two Chimneys, 250m and 300m tall, in Secunda, RSA
— P. Noakowski, R. Cowley
- Introducing a New Hot Camera System for Videoing Chimneys Internally, On-Line
— G. Oudin
- Investigation of a 30 Year old 200m Tall Power Plant Chimney
— V. Rosetnic
- Failure Probability und Load Factors
— N.R. Bierrum
- A Home Page for CICIND
— H. Bottenbruch.
- A User's Guide to CICIND's Home Page
— Riverprint Ltd
- A Calculation Method for Fatigue Life of Steel Chimneys under Cross-wind Oscillations
— H. Von Koten
- Two Steel Chimneys having Particular Design with regard to Oscillation Behaviour
— N. Ferlic
- Heightening of a Brick-Built Chimney by a Guyed Steel-Top
— M. Prinz & V. K. Roels
- Sixty Years Experience of Steel Chimney Erection
— Max Beaumont
- Overview of the History and Word of IVS
— G. Berger

CICIND REPORT 14-2 September 1998

- Wind loads and design for chimneys
— B.J. Vickery
- Measurements of the test chimney at Aachen IJiversity
— H. van Koten
- The revised CICIND Model Code for Concrete Chimneys: Part A. The Shell
— N.R. Bierrum
- Comparison of crack limitation in CICIND and EC2
— P. Noakowski, et al.
- The earthquake response of reinforced concrete chimneys
— J. Wilson
- Analysis of concrete chimneys for mining shocks
— R. Ciesielski
- Al Arish chimney linings failure and subsequent repairs
— D.T. Smith
- Repair of a ceramic brick liner in wet FGD service using borosilicate glass blocks
— A. de Kreij

CICIND REPORT 15-1 March 1999

- No noise is good noise - development in noise assessment and control
— K.R. Tompsett
- A new automatic device for cleaning the inside of chimneys
— J.E. Asteinza & C.G. Florez
- Vortex induced vibrations of line-like structures
— S. Ole Hansen
- Measured damping decrements of steel chimneys and their estimation
— G. Berger & C. Verwiebe
- Fatigue and damping of chimneys
— H. van Koten
- An assessment of EC8 rules für the seismic design of reinforced chimneys
— V. Rosetnic
- Monitoring and computer-aided assessment of existing chimneys
— M. Lechman
- Brick lining versus Pennguard lining - can Pennguard win?
— P. Noakowski , A. de Kreij

CICIND REPORT 15-2 September 1999

- Control of Crack Width — Comparison of Predictions in CICIND and EC2
— N. R. Bierrum, P. Noakowski, H.G. Schäfer und M. Woitzik
- The New CICIND Model Code for Steel Chimneys
— B.N. Pritchard
- Earthquake Design and Analysis of Tall Reinforced Concrete Chimneys
— J. L. Wilson
- Modification of Aerodynamic Forces due to Deviation from Circular Cross Section
— J.K. Galsworthy and B.J. Vickery

Steel Flues in a 300m R.C. Chimney. Excessive Vibrations; arrangements for strengthening
— R. Ciesielski
Nickel Containing Materials in Flue Gas Desulfurization Equipment
— W.H.D. Plant und W.L. Mathay
Clad Steel Plates for Chimney Liner Applications in Japan
— H. Akanabe, Y. Yanamura, Y. Saito
Protection of Chimneys against Acid Attack and Environment Conditions
— B. Ertz, A. Kochan
Circular Reinforced Concrete Shaft Cracking Caused by Moisture Differential
— P. Moncarz, R. Coetzee, P. Noakowski
Stabilisation of Cracked Chimney Flues at Matimba Power Station, RSA
— R. Coetzee, P. Moncarz, P. Noakowski and M. Stegeman

CICIND REPORT 16-1 March 2000

Wind tunnel tests on the effect of turbulence on the cross-wind loading of chimneys
— van Koten und Hansen
Standby chimneys & chimneys for by-pass operations
— Jezek
Control of crack width in CICIND and EC2
— Bierrum
Wind turbines on tall reinforced concrete chimney stacks
— Bendix
The plasticity behaviour of potassium silicate mortars
— Sipek und Kolisko
Experimental evaluation of the temperature distribution in chimneys under sun exposure
— Lechman
A review of codal provisions for reinforced concrete chimneys subject to wind loading
— Menon

CICIND REPORT 16-2 September 2000

Code recommendations for the aseismic design of tall reinforced concrete chimneys
— J. Wilson
Experience of the Marmara and Bolu earthquakes in Turkey, 1999
— T. Tunca
Earthquake damage to chimneys at Taichung Power Station, Taiwan, 1999
— Lin Hung, Chen Ming-chin
Practical aspects of fabricating nickel-chromium alloys: Lining and Overlaying
— D. Heath
Clad plate for air pollution control equipment
— H. Akabane, Y. Yamamura, Y. Saito
Interference effects to the vortex-induced vibrations between large chimneys of different diameters and lengths
— H. Ruscheweyh, A. Trätner
Blowing in the wind: A critique of the EC1 wind speed proposals
— A. Allsop

CICIND REPORT 17-1 March 2001

Damage observations from the Izmit (Kocaeli), Turkey earthquake of August 17, 1999
— P. Moncarz, L. Shusto
A preliminary analysis of the Tupras Refinery stack collapse during the Kocaeli earthquake
— S. Kilic, P. Moncarz & P. Noakowski
Seismic behaviour of reinforced concrete chimneys
— P. Riva
The design and construction of a 100m tall double-skin, free-standing chimney
— D.T. Smith
Interesting retrofits and repairs to steel chimneys
— R. Warren
Calculation of the damping of chimneys
— H. van Koten
GRP Liners - Review by the CICIND Committee Chairman
— S. Reid

CICIND REPORT 17-2 September 2001

Seismic load reduction factors for concrete chimneys: a probabilistic assessment
— J.L. Wilson
A challenging chimney retrofit project for a steel producing company in Ontario, Canada
— A. Bhowmik
Long-term behaviour of reinforced concrete industrial chimneys in Romania and
retrofit solution for the No 2 chimney of the Isalnita-Craiova power plant
— L. Naum, D. Furis

ACI 307-98 and CICIND 2001. Comparison of in-line wind loads and reinforcement
—N.R. Bierrum
Steel stacks for gas turbines
—N. Ferlic

CICIND REPORT 18-1 March 2002

Aerodynamic drag coefficients for multi-flue steel chimneys
— Z.A. Zuranski, J. Kawecki
Strengthening of chimney shafts using CFRP composites
— M. Lechman
Flue gas liners under extreme working conditions
— B. Kremser
Desulphurisation of waste gases and their discharge - Review of the situation in Poland
—R. Ciesielski
The dismantling of unused reinforced concrete chimneys and their use for wind turbines
—H. Bendix
Rheological distribution of stresses in the shafts of concrete industrial chimneys
— R. Ciesielski, R. Oruba

CICIND REPORT 18-2 September 2002

Seismic performance of the Pennguard chimney lining system
— J.L. Wilson, A. de Kreij
Comparison of Eurocode EC1 Part 4 wind Loads with those calculated by
the CICIND Steel and Concrete Codes
—P.Freathy
Non-linear response of the 115m Tupras refinery stack subjected to the 1999 earthquake
—N. O. Akinci, S. A. Kilic
Replacement of a brick liner with steel flue. Design and construction considerations
—P. Noakowsk, P. D. Moncarz
Combined cycle gas turbine stacks
—R. M. Warren

CICIND REPORT 19-1 March 2003

FRP liner with a heating - a measure to prevent the formation of particles and droplets
—B. Ertz
Improving the inflow into a chimney
—H. Ruscheweyh
Use of different coating systems to reduce maintenance requirements of RC chimneys
—A. Kochan
The effects of poor workmanship on the normal stresses in RC chimneys
— M. Lechman
5. Vibration dampers for steel chimneys
— H. van Koten
Mining subsidence and shock influence on chimneys in Upper Silesia
—R. Ciesielski, K. Koziol

CICIND REPORT 19-2 September 2003

Experimental study to investigate the cyclic behaviour of reinforced concrete chimney sections with openings
— J. L. Wilson, S.A. Kilic
Stabilization of a nearly collapsed brick liner in a concrete chimney and reuse of die liner
—A. Bhowmik
Maintenance of brickwork linings and environmental impact
— C. Gonzalez Florez, J. del Solar Bermejo
Fundamental procedures and techniques for planning, repair retrofit and maintenance of non-metallic expansion
joints and chimney seals to 600 C for outages
—H. Reichel, T. Brown
An approach to the capacity design of reinforced concrete chimneys
—V. Rosetnic

CICIND REPORT 20-1 March 2004

Rehabilitation of a concrete chimney by reducing its height
—D. Cretu, L. Naum, E. Tulei
Rehabilitation of a concrete chimney using pre-stressing rings
—A. Popaecu, I. Dumitrache, I. Mateescu
The dynamic cross-wind response of two rectangular section chimneys
—P.E. Freathy, D.M Sykes
New coating systems for sealing and protecting the inner surfaces of brick liners
—A. Kochan
Instrumentation of a high chimney, aiming to evaluate the real state and to survey its seismic behaviour
—A. Korbl, et al

CICIND REPORT 20-2 September 2004

- Replacement of a Stainless Steel Liner, Diameter 2.3 m in a 160 m high Chimney
— B. Kremser
- Design and Construction of a 67 m Steel Chimney - Isle of Man: Waste to Energy Plant
— G. Pinfeld
- Early Defects in Surface Protection Systems due to Sulphate Contamination
—A. Kochan
- Fatigue Problems of Steel Chimneys due to Vortex Vibrations in the Second Mode
— C. Verwiebe
- Creep of Concrete Platforms. Design on concrete Platforms in Multi-Flue Chimneys
— B. Ertz, H. Hoffmeister
- Wet Stack Application – Chimney Operation without flue gas reheating after FGD
— M. Breddermann, P. Noakowski, J. Lenz
- Retrofit of GRP flues at Eggborough Power Station
— G. Eastman

CICIND REPORT 21-1 March 2005

- Moneypoint Chimneys
— Hayes, T., Quigley, F
- Study of GRP Tubular Structures Subject to Bending
— Lechman, M
- Chimneys for Peat-Fired Power Plants - Examples of Lough Ree Power and West Offaly Power, Ireland
— Hoffmeister H., Draese, R
- Stability of Codes
— Oudin, G
- Reinforcement around the Openings of Steel Chimneys
— van Koten, H
- Antenna Carriers of Steel Tubes - Fatigue failure behaviour due to vortex shedding
—Rost, M., Harling, A.; Breddermann, M.; Noakowski, P
- Concrete Chimneys - Design and Construction for an Economical Solution
—Smith, T

CICIND REPORT 21-2 September 2005

- Evaluation of Steel self-supporting Interceptor Smoke Stacks Endurance Life
— V.A. Syiykh, R.G. Gubaidulin, M.R. Gubaidulin, A.S. Shmatkov
- Aberthaw power station prepares brick flues for FGD by installing Pennguard®
—Albert de Kreij, Gary Eastman
- Design of a 61 m Steel Chimney under Combined Earthquake and Wind Loading
— Michael Angelides and Lena Zannaki
- Modern methods of reconstruction of chimneys
—Alexander Elshin, Vladimir Astashkin, Vladimir Luzhkov
- The New German Guidelines for the Maintenance of Concrete Chimneys
—Andreas Kochan, Juergen Lenz
- New Application of Vibration Dampers to reduce along wind loads
—Gilles Oudin
- Scanliner Diagnoses
— Serguie Sushchev
- The Kyoto Protocol and conditions of chimney service in Russia
— Alexander Elshin, Vladimir Astashkin, Vladimir Luzhkov

CICIND REPORT 22-1 March 2006

- Corrosion allowance in View of the European Standards
—Georg W. Berger
- Design of a Chimney with GRP Liner for Low and High Temperature Operation
— Victor Bochicchio
- Increase in Height of 42 m chimney to 90 m in Waterford, Ireland
—Geoffrey Pinfeld and Carsten Madsen
- Analysis of the Efficiency of Advertisement on Chimneys
—Alexander Elshin
- Study of Interference effect of Multiple Heater Mounted stacks placed in one line
—Ashwini Oke
- Ring stiffeners for steel chimneys
—Henk van Koten
- Investigation of the cyclic behaviour of reinforced Concrete Chimney Sections with Openings orientated to be shear critical
— John L. Wilson

CICIND REPORT 22-2 September 2006

Abnormal behaviour of Chimney Brickliners due to underestimated Gas Flow

— Mario Poli, Giovanni Di Poi

Some experiences with surface protection of reinforced concrete chimneys

—Andreas Kochan

Solar Tower for a Thermosolar Power Plant

—Ignasi Salvador Villa

Rumanian Industrial Chimneys designed and built in 1965-1 985

—Laurentiu Naum

Why and how to increase the Structural Damping of Structures

—Gilles Oudin

EDF Energy Cottam modifies 200 m high, multi-flue chimney for Wet Stack Operation

—Gary Eastman, Albert de Kreij

Nonlinear thermal behaviour of a bricklining during heating-up

— Riekie Coetzee, Piet Willemse

CICIND REPORT 23-1 March 2007

Dynamic Fatigue along wind for tall, slender structures

—AshwiniOke

Automatic Inspection Systems for Industrial Chimneys

— Carlos Martin Diaz dc Espada

Chimney Design with CICIND, DIN 4133 and EURO; A Critical Review

— Gerrit K. Verboom

Design and construction of three 75 m high Steel Chimneys placed in a triangle and surrounded by louver rings

— Carsten Madsen, Brian Madsen

Access Solutions for Chimneys and Tall Structures

— Andrew Kelly, Colin McCurdy, Darren Smith

Cross Wind Tests on a Concrete Chimney with high Reynolds Numbers

—Henk van Koten

Resistance of Non-Circular Cross-Sections of RC Chimneys

—Marek Lechman

Conversion of a 180 m high chimney

— Bernhard Kremser, Ulrich Wanzek, Stefan Lindner

Noise attenuation for Chimney Engineers

—Steven Reid

Performance of the Pennguard® Block Lining System during large power plant fires

—Albert de Kreij